

WE HEREBY CERTIFY

The products described below, manufactured by SACOPA, S.A.U., a company of the Fluidra Group, are manufactured and assembled in Spain, CE origin. Complies with the technical characteristics that are specified in our catalogue and/or in the technical file published for it.

Code	Description
00249	SK-15L PH B.STD TR
00250	SK-15L PH B.STD TC
00251	SK-15L PH B.CON TR
00252	SK-15L PH B.CON TC
00257	SUM D180 PH 2"BSP AVX
00258	SUM C210 PH 2"BSP
00271	SUM D210 PP 2"BSP
00295	BQ-I D115,5 PH 2"-D50
00298	BQ-I D115,5 PH D63PN6-D50
00300	BQ-A D115,5 PH D63PN6-D50
00301	BQ-A D115,5 PH 2"-D50
00303	BQ-F D107 PH 2"-D50
00330	BQ-I D115,5 PP LINER 2"-D50
00334	BQ-I D115,5 PP 2"-D50
00349	NICHO STD PH
00355	NICHO PS PH
06481	BQ-I D90 PP 2"-1½"BSP
06967	NICHO MINI PH
11302	SK-17,5L PH B.STD TC EMB
11304	SK-17,5L PH B.CON TC
15862	REGULADOR DE NIVELL
15863	BQ-F D107,5 PH -D63
20140	BQ-F D107 PH D63PN6-D50
22379	CANTONERA 90 22X195 PLASTICO
22380	CANTONERA 90 22X245 PLASTICO
22381	CANTONERA 90 22X295 PLASTICO
22382	CANTONERA 90 22X335 PLASTICO
22383	CANTONERA 90 35X195 PLASTICO
22384	CANTONERA 90 35X245 PLASTICO
22385	CANTONERA 90 35X295 PLASTICO
22386	CANTONERA 90 35X335 PLASTICO
24413	BQ-I D88 PH D50PN10-D32


24415	BQ-A D86 PH D50PN10-	
27837	SUM D200 PH 2"BSP-1½"BSP AVX	
27839	SUM D200 PH 2"BSP-1½"BSP REJ	
35418	BQ-A D90 PH D63PN06-D50	
56378	EMBORNAL NORMA PF REIXA PLANA	
56380	SUM D189 PP TM NORMA	
56498	BQ-I D115,5 PH 2"-D50 NORMA	
71209	EMBELLECEDOR FLEXINICHO	
74395	ADAPT. FLEXIMINI TUBS BLANC	
75971	CAIXA CONNEXIONS UNIK	
75972	CAIXA CONNEXIONS	
76493	BROQ. PF. ENCOLAR D50 INT	

That these products passed satisfactorily the control tests established by the Quality Assurance System.

That SACOPA, S.A.U., makes its products fulfilling the requirements of the international quality standard ISO-9001:2015, certified by LRQA with approval number 00040838.

That these products are guaranteed against any manufacturing defect during the legal guarantee of each country, with the exception of negligence, wrong installation or indue use of them.

Sant Jaume de Llierca (Girona-Spain), June 2026.



Manager

SACOPA

